

**P1-631** <追加加工>

赤枠内の図面にL寸法を追加



Alteration  
追加加工



型式 **A** - **B** - **C** - **T** - **L** - (SS・SQ...etc.)  
SLI - A120 - B50 - C20 - T10 - L100 - SS15 - M5




タップ穴径	b(最小値)
3・4・5	0.8
6・8・10	1.0

Alterations	タップ穴加工				溝加工																																
	側面にタップ穴1コを追加	側面にタップ穴4コを追加	上面にタップ穴2コを追加	上面にタップ穴4コを追加	底面に溝加工																																
<b>Code</b>	<b>SS</b>	<b>SQ</b>	<b>JD</b>	<b>JQ</b>	<b>TM</b>																																
<b>Spec.</b>	SS=指定1mm単位 指定方法 SS8-M5 ■タップ穴径選択 寸法 <table border="1"><tr><td></td><td>呼び径</td></tr><tr><td>3</td><td>4</td><td>5</td><td>6</td><td>8</td><td>10</td></tr></table>		呼び径	3	4	5	6	8	10	SQ・Y・G=指定1mm単位 指定方法 SQ12-Y15-G10-M5 ■タップ穴径選択 寸法 <table border="1"><tr><td></td><td>呼び径</td></tr><tr><td>3</td><td>4</td><td>5</td><td>6</td><td>8</td><td>10</td></tr></table>		呼び径	3	4	5	6	8	10	JD・Y・G=指定1mm単位 指定方法 JD40-Y12-G30-M8 ■タップ穴径選択 寸法 <table border="1"><tr><td></td><td>呼び径</td></tr><tr><td>3</td><td>4</td><td>5</td><td>6</td><td>8</td><td>10</td></tr></table>		呼び径	3	4	5	6	8	10	JQ・F・Y・G=指定1mm単位 指定方法 JQ15-F20-Y12-G50-M6 ■タップ穴径選択 寸法 <table border="1"><tr><td></td><td>呼び径</td></tr><tr><td>3</td><td>4</td><td>5</td><td>6</td><td>8</td><td>10</td></tr></table>		呼び径	3	4	5	6	8	10	TM・F=指定1mm単位 指定方法 TM-F10 溝深さ1.5mm 2≤TM・F TM+F≤(A/2)-2
	呼び径																																				
3	4	5	6	8	10																																
	呼び径																																				
3	4	5	6	8	10																																
	呼び径																																				
3	4	5	6	8	10																																
	呼び径																																				
3	4	5	6	8	10																																
<b>¥/1Code</b>	500	1,300	800	1,300	1,600																																

<訂正用>

①



②

